



All dimensions are imperial unless stated.



	T1	T2	T3	T4	B1	B2	B3	B4	L1	L2	L3	L4	LL1	LL2	LL3	A/F
04030	1/4	1/4	1/4	1/4	0.25	0.25	0.25	0.25	0.56	0.56	0.69	0.69	0.935	0.935	1	0.625
04031	3/8	3/8	3/8	3/8	0.375	0.375	0.375	0.375	0.56	0.56	0.72	0.72	1.06	1.06	1.095	0.75
04032	1/2	1/2	1/2	1/2	0.5	0.5	0.5	0.5	0.75	0.75	0.943	0.943	1.312	1.312	1.38	0.875
04033	3/4	3/4	3/4	3/4	0.687	0.687	0.687	0.687	0.75	0.75	0.96	0.96	1.4	1.4	1.522	1.125

A/F dimensions are imperial unless stated.



	T1	T2	T3	T4	B1	B2	B3	B4	L1	L2	L3	L4	LL1	LL2	LL3	A/F
04030	1/4	1/4	1/4	1/4	6.35	6.35	6.35	6.35	14.22	14.22	17.53	17.53	23.75	23.75	25.4	0.625
04031	3/8	3/8	3/8	3/8	9.53	9.53	9.53	9.53	14.22	14.22	18.29	18.29	26.92	26.92	27.81	0.75
04032	1/2	1/2	1/2	1/2	12.7	12.7	12.7	12.7	19.05	19.05	23.95	23.95	33.32	33.32	35.05	0.875
04033	3/4	3/4	3/4	3/4	17.45	17.45	17.45	17.45	19.05	19.05	24.38	24.38	35.56	35.56	38.66	1.125